Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA			(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDING: 01		R 09/12/2017		
	_	HAL034084	B. WING		09/12/	2017
NAME OF P	ROVIDER OR SUPPLIER			TATE, ZIP CODE		1
	H VILLAGE	5100 LAN	SALEM, NC	27105		
FUKSTII			ID i	DROVIDER'S PLAN OF CORRECTI	ON D. RE	(X5) COMPLETE
(X4) ID PREFIX TAG	ARTAGU DECICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		DATE
{C 000}	Initial Comments		{C 000}			
	Report of Biennial by Dennis Harrell	Follow Up Construction Survey on 9-12-2017.				
	Many deficiencies Further action is re	were still not corrected. equired.				
(C 166) Housekeeping-Maintained Free of Hazards			{C 166}	1)	
	10A NCAC 13F .0 FURNISHINGS (a) Adult care hor (5) be maintaine orderly manner, f hazards; (e) This Rule shafacilities.	d in an uncluttered, clear and ree of all obstructions and all apply to new and existing			!	
	5. Based on obsiline extended into drain lines that a inches above the by Code, could be contaminated.	met as evidenced by: servation, the ice machine drain to the floor drain. Ice machine re not maintained at least 2 floor or floor drain, as required cause the ice to become 2017 and 7-12-2017: de drain was laying directly on the		Maintance man a within 2 days take over. drain no longe the floor.		10/20/1
(C 189) Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT		{C 189}				
	mechanical an	TS g and all fire safety, electrical, d plumbing equipment in an adu ll be maintained in a safe and	it		·	
Division	of Health Service Regula		SIGNATURE	TITLE Admic	`	(X6) DATE

BUFK24

PRINTED: 10/03/2017 FORM APPROVED

Division of Health Service Regulation (x3) DATE SURVEY							
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION		COMPLETED			
AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A, BUILDING:	01		- 1		
					09/12/2017		
		HAL034084	B. WING		09/12	/201/	
	DOLLERS OF CHERNIES	STREET ADD	RESS, CITY, S	STATE, ZIP CODE		- 1	
NAME OF P	ROVIDER OR SUPPLIER		SING DRIVE			1	
FORSYT	H VILLAGE		SALEM, NO				
			ID	PROVIDER'S PLAN OF CORRECTI	ON	(X5) COMPLETÉ	
(X4) ID	Zana : /EACH DESIGNENCY MUST BE PRECEDED OF FORE		PREFIX	(EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRO	4 SHOULD BE		
PREFIX	REGULATORY OR L	SC IDENTIFYING INFORMATION)	TAG	DEFICIENCY)		1	
{C 189}	Continued From pa	age 1	{C 189}		!	1	
,		apply to new and existing			i	1	
	facilities with the ex	xception of Paragraph (e)	l I		!	- 1	
	which shall not and	bly to existing facilities.	1		!	1	
	William Street Total			İ	i	1	
	ı						
	This Rule is not m	et as evidenced by:				1	
	Based on obse	rvation, the fire alarm system	}	Admin had fire co		1	
ĺ	was not being mail	ntained in a safe and operating		Thurun Mad thre C	MICOUNC	\	
	condition. Fire ala	rm systems that do not work all residents and staff.)	come out as upda		10/24/1-1	
\	Finding on 7-12-20	017 and 9-12-2017:		which a man	area :	DOM I	
	a The corridor sn	noke detector near bedroom 30		the Sixtem		اخالسالنا	
activated when tested with smoke but failed to			-	the System.		idiali (l	
sound the fire alarm system .			Ì	All issues resonud	ļ	111211	
	Finding on 9-12-20	017:	j	1000.		mant 1	
ļ	 b. The fire alarm 	system worked when tested but				i''	
	the display states	it is "Disarmed" and also states				1	
the following need to be checked; i. 023 Duct			j	Admin had G.	ana Mari	ا ـ ۱ ـ (من	
1	ii. 030 Duct, 2 H	leat		Admin had fin c	umpvia.	[M24][7]	
	iii. 62 DS 3		ļ	Come out to upo	aled	ו ביו ואולוג (
l	iv. 074 Duct		ļ	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	W (Ca)-		
i	v. 112 Duct Alar			the sustem.		11120117	
	vi. 001 FCPS St	pervision		Adianuman sandu		1, 1,	
İ		alarm system was impaired, a	Ì	All issuses resolv	e0	,	
1	Flan of Protection	was accepted in which the begin a fire watch to continue	Ì			!	
	until the fire alarm	n system is repaired and certified	d i			,	
1	as working prope					ļ	
1	•	-	ì				
	3. Based on obs	ervation the required one-hour	. 1				
1	fire rated walls ar	nd/or ceilings were compromised	2			i	
1	in several location	ns. Holes and penetrations that	1			Į	
1	are not sealed Wi	ith materials approved for use in ed construction present the	}			ļ	
	noccibility that a	fire that begins in one space car	1			:	
1	quickly enread to	other areas of the facility.	-	4		Į	
	Findings on 1-4-2	2017 and 5-2-2017 and					
	7-12-2017 and 9	-12-2017:]	İ			
	c. Hole in the ce	iling in the outside AC room nea	ır				

PRINTED: 10/03/2017 FORM APPROVED

Division of	of Health Service Re	gulation		- ANIOTOLIOTION	(X3) DATE S	URVEY		
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION		COMPLETED				
AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING: 01		l R				
		HAL034084	B. WING			/2017		
				TATE 219 CODE				
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 5100 LANSING DRIVE								
FORSYTI	H VILLAGE		SALEM, NO					
	PROVIDER'S PLAN OF CORRECTION ((X5) COMPLETE		
(X4) ID PREFIX	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX TAG (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		PRIATE	DATE		
TAG								
10.4001	Continued From pa	2	{C 189}		1			
{C 189}			. ,			- 1		
	the maintenance ro	oom. ency gas furnaces were						
ļ	installed in all 4 out	tside AC rooms in 2008 or		ļ	'	Ì		
	later. The furnace	flues are 3 inch PVC pipes			ı			
	that extend up thro	ugh the one-hour fire protected he flues were protected with a			I	- [
	listed fire collar as	required.				1		
	•			Δ	!			
	 Based on observation, some corridor doors will not close and/or latch to resist the passage of 			All doors were (and fixed. All d Close properly	\Dak.			
	fire and smoke. C	orridor doors that do not close	-	and Cival Au 1	J	Sa il		
	completely and late	ch present the possibility that a	ļ	Tha. Alla	ω_{l3}	10130117		
ĺ	fire that begins in o	one space can quickly spread the remainder of the facility.	1	mase broberin		1 1 1		
	Findings include the	ne following doors on 1-4-2017		1				
	and 5-2-2017 and	7-12-2017 and 9-12-2017:		i				
1	b. The door to be	droom 14 does not fit the o be resistant to the passage of	[١		
	smoke.]					
1	1					i		
1			1					
l			į					
]								
1	ļ		ļ	!				
1	ļ					ļ ī		
	İ		!					
	1			İ				
1								
	i							
1			1	į				
1	1]			!		
						i		
			ì					
	i							